

BEFORE

AFTER



IN PARTNERSHIP WITH

PAUL DAVIS
RECOVER • RECONSTRUCT • RESTORE



DESCRIPTION

A stack of apartment units were heavily damaged by a fire. Shrink-wrap was applied to the structure to encapsulate the damaged area following demolition from the rest of the building and the outside elements.

PROJECT DETAILS

Client:	Paul Davis
Event Type:	Fire
Building Type:	Apartment Building
Square Footage:	1400
Scope:	Wrap

STORMWRAPPERS
EMERGENCY ENCLOSURE EXPERTS

888-8WRAPIT
STORMWRAPPERS.COM

Copyright © 2025. All Rights Reserved.

CASE STUDY



IN PARTNERSHIP WITH




DESCRIPTION

A rare tornado in upstate NY caused a large tree to fall onto the house, causing a large portion of the front of the house to be split outwards. After working with a tree removal service to get the tree removed off the house and removed from the property, StormWrappers temporarily secured the front wall back to the house structure then shrink-wrapped the roof and 2nd story wall to dry in the building envelope.

PROJECT DETAILS

Client:	Rock Emergency
Event Type:	Fallen Tree, Tornado
Building Type:	House
Square Footage:	3000
Scope:	Wrap, Demo, Temp framing, Shoring



888-8WRAPIT
STORMWRAPPERS.COM